

## Notice of Change of Uninterruptible Power Supply for DFL7160

Dear customer:

We are delighted to hear that your company is doing well and would like to offer our sincere thanks for your continued support. The following document reports the details relating to the matter indicated above. We apologize for any inconvenience that it may cause.

DISCO

### Notice

---

Since production of the current optional accessory uninterruptible power supply has been stopped, we will be changing to a newer model.

Along with the change to the newer model of the uninterruptible power supply, the breaker will also be changed.

### Affected model

---

DFL7160

### Start period

---

We plan to use the newer model for machines shipped from October 2013 onward.

### Changed parts

---

Uninterruptible power supply (internal type) part number

Machine name	Before change	After change
Uninterruptible power supply (main body)	DGCDPU06002-0	DGCN11A5005-0

Machine standard specification	Before change	After change
Leakage current	17mA or less	23mA or less

Since the leakage current for this machine's standard specification will change along with the change in the uninterruptible power supply, the rated sensed current will change from a 30mA breaker to a 50mA one.

Breaker rated sensed current

	Before change	After change
Rated sensed current	30mA	50mA

If using a protective leakage breaker at the plant facility, you should prepare a harmonic countermeasure part with a sensed current of 50mA or more.

As well, the newer model of the uninterruptible power supply is already being used in other machines made by DISCO.

### Inquiries

---

Please direct any inquiries regarding this matter to a DISCO sales representative or service affiliate.

---