

# Technical Newsletter



#tnl2015-0014e

# 1 / 1

## DFL7361 Error Correction Requirement in Installation Manual

### Introduction

---

Errors were found in the ambient temperature for the storage and transport environment indicated in the Installation Manual for the DFL7361. Please check the content and correct the error.

### Affected Installation Manuals and section with errors

---

Part No. of Installation Manual		Section
Japanese	URGSNJHI00A	Section 3-3 [Environment for Storage and Transport] of Chapter A
English	URGSNEHI00A	

### Correction

---

Wrong		Correct	
Ambient temperature	Storage : 15 to <u>40°C</u> Transport : 15 to <u>40°C</u> <u>(Excluding laser optical parts such as a optical lens and mirror.)</u>	Ambient temperature	Storage : 15 to <u>30°C</u> Transport : 15 to <u>30°C</u>

### Inquiry

---

If you have any questions on this matter, please contact your nearest DISCO office or DISCO service office.

---