





6000/600 Series: Production Discontinuation of Some UV Lamps

Notice

Production of some UV lamps in use with the UV irradiation unit [optional accessory] has been discontinued. Because of this, we change to new-type UV lamps. We install the new-type UV lamps in the machines to be shipped in March 2018 and beyond in order.

Changes

- The appearance of the UV lamps changes.
- There is no change in the effects of UV irradiation or the rating life.
- The UV lamps that have gone out of production are two types.

Existing type (production discontinued)		New type
	➔	
Part No. DEAF6BLB01-0		Part No. DEAF6BL-02-0
	➔	
Part No. DEAF4BLB01-0		Part No. DEAF4BL-02-0

Applicable model

Series	Applicable model
6000 series	DFD6240/DFD6340/DFD6341/DFD6450/DFD6240 RR Specification
600 series	DFD640/DFD641/DFD651/DFD681/DFD691

Replacement

When replacing any UV lamp, be sure to replace all the UV lamps in use with the UV irradiation unit [optional accessory] by the new-type ones.

For the type and number of UV lamps and the replacement procedure, refer to the Maintenance Manual included with the machine.

Inquiries

Please contact your local DISCO sales representative or DISCO customer engineer if you have any questions regarding this matter.