Technical Newsletter

#tnl2014-0013e # 1 / 1



The Machine May Malfunction Due to LED Lights at Your Plant

Notice

The phenomenon that the machine malfunctions has only occasionally occurred at our customers' plants that have introduced LED lights.

The conditions leading to malfunction include the following:

- The intensity of the LED lights
- The period of pulse emission of the LED lights agrees with the sensor period of the machine.

Phenomena that have actually occurred

After changing the lighting at the customers' plants from fluorescent lamps to LED lights, the following phenomena have been reported:

- The cassette size is wrongly detected.
- "No cassette" error occurs even when a cassette has been put.

Please take note that if the machine malfunctions due to LED lights at your plant, any measures against the malfunction will be taken on a chargeable basis.

Inquiries

Please contact your local DISCO sales representative or DISCO service office if you have any questions regarding this matter.