

Technical Newsletter

#tnl2018-0015e

1 / 1



DFG8340 Maintenance Manual Request for Correction of Errors in the Part Number for the Seal Unit

Purpose of this Technical Newsletter

We have found some errors in the part number for the seal unit described in the Maintenance Manual for the DFG8340.

Applicable Maintenance Manual

Applicable model	Part No. in the Maintenance Manual	
DFG8340	English	UNWSMEH001A, UNWSMEH001B, UNWSMEH001C
	Japanese	UNWSMJH001A, UNWSMJH001B, UNWSMJH001C

Correction details

Item	Part No. [wrong]	Part No. [correct]
Seal unit	LNDR-010143-2	LNNR-010143-4

Inquiries

Please contact your local DISCO sales representative or customer engineer if you have any questions regarding this matter.
